


**Figure 6-49
TYPICAL RUNAWAY TRUCK RAMP SIGNING AND MARKINGS**



Notes:

1. Place Type 'J' Delineators at 15 m centers. See Figure 6-45.
2. Place NO STOPPING ANY TIME, R26A(S) signs at 75 m centers.
3. Additional RUNAWAY TRUCK RAMP 1 MILE and RUNAWAY TRUCK RAMP 1/2 MILE, W30 signs may also be placed in the median on a one-way roadway.
4. Place 3 - Type 'F' Delineators at 150 m centers, preceding and following the Runaway Truck Ramp. See Figure 6-45.
5. Additional advance RUNAWAY TRUCK RAMP (2 MILES, 3 MILES, etc.) W30 signs may be added as necessary.
6. Overhead signs may be substituted for ground mounted signs.

LEGEND

← Direction of Travel

NOT TO SCALE